


Bellevue Residence Remodel

Summer 2003



Before: Unfinished basement with dark finishes

The basement of this Bellevue ranch house had never been finished, and had minor water damage. We updated the design to meet the needs of the current owner, including a sewing and utility room, improvements to an existing guest room, conversion of an unused workshop into a TV room, construction of a full bath, and new finishes throughout.



After: New hallway, bathroom, sewing room, and TV room.